



### Structure of the ПМС starter designation:

ПМС X X X X X X - ОМХ Х

Starter type: ПМС

Rated voltage:

1 - 220 V, 50 Hz;  
2 - 380 V, 50 Hz

Starter size:

1, 2, 3, 4, 5

Index for degree of protection:

3 - IP23

5 - IP55 (without ammeter)

6 - IP56 (without ammeter)

Version by purpose:

1 - non-reversing;

2 - reversing;

3 - non-reversing, with winding switching from "star" to "delta"

Index for availability of control elements:

0 - without control elements;

1 - with load switch without control elements;

2 - with control push-buttons;

3 - with control push-buttons and load switch;

4 - with control push-buttons and selector switch;

5 - with control push-buttons, load switch and selector switch

Index for additional elements:

A - with ammeter;

No index — without ammeter

ОМ climatic version, installation categories 1, 3, 4

Rated current (see table)

Supply with acceptance:

- RMRS

- RRR

- VP



|                                          |
|------------------------------------------|
| Junction boxes                           |
| Metal junction boxes                     |
| Plug transformers                        |
| Push-button stations                     |
| Junction boxes with protection unit KC35 |
| Power boxes with protection unit KC35    |
| Interference suppression filters         |
| Electromagnetic starters                 |
| Cam switches                             |
| Cam selector switches                    |
| Appendix 1. Starters                     |